

# Oil Field Environmental Incident Summary

**Incident:** 20140213082723 **Date/Time of Notice:** 02/13/2014 08:11

**Responsible Party:** Hess Bakken Investments II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** DAHL 15-22H

**Field Name:** DOLLAR JOE

**Well File #:** 19448

**Date Incident:** 2/12/2014 **Time Incident:** 0830

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 97

**Sec:** 22

**Qtr:**

**Location Description:**

**Submitted By:** Jason Henry

**Received By:**

**Contact Person:** Jason Henry  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Miles

**Distance Nearest Water Well:** 0.5 Miles

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	barrels	0	barrels		
Brine	1.5	barrels	0	barrels		
Other	0	barrels	0	barrels	2	barrels

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/19/2014

**Clean Up Concluded:** 2/21/2014

**Risk Evaluation:**

N/A

**Areal Extent:**

Approximately 0.65 acres on location and 0.24 acres off location (south of the well location)

**Potential Environmental Impacts:**

The release occurred aboveground and no potential receptors were observed in the immediate vicinity of the release. A vacuum truck was dispatched to recover the free liquid from around the wellhead.

**Action Taken or Planned:**

The cause of the stuffing box failure is under further investigation. A vacuum truck was dispatched to recover the free liquid in the vicinity of the wellhead. The impacted material will be excavated, stockpiled, and transported off-site for proper disposal.

**Wastes Disposal Location:** Transported off-site to a properly permitted disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 2/13/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 15:35 2/13/14.

At the time of inspection, no remediation work had been done. The crude oil and produced water sprayed out from the stuffing box and covered an area approximately 330' by 50'. The spray becomes very light toward the end of the sprayed area.

Followup necessary to ensure proper cleanup of location.

---

**Date:** 2/13/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Leak from stuffing box sprayed off the south side of the location. Followup is necessary.

---

**Date:** 6/25/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site 12:15 6/25/2014.

No sign of spill that occurred during the winter. Remediation is considered complete.

No followup is necessary.

---

**Date:** 7/16/2014    **Status:** Inspection

**Author:** Washek, Sandi

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 10:45 a.m. Sunny and light wind from the southeast at 10 mph. Area to the south of the pad has been cultivated and seeded to oats. Observed that the weeds in the area have been sprayed. The rest of the area is well vegetated with no signs of stress. On south side of gravel road, there is a 3' X 4' stained area along the fence line in the hay field. Rest of road ditch and field vegetation show no signs of stress.